

Moles · Sjerve

Phased Array

IIW Handbook

Table of contents

Foreword

1	Introduction	1
1.1	Why an IIW Phased Array Handbook?.....	1
1.2	IIW	1
1.3	Handbook layout	2
	References	2
2	Ultrasonic phased array principles and design	3
2.1	Ultrasonic phased array instruments	3
2.2	How phased array probes work	3
2.2.1	Delay laws.....	5
2.2.2	Constructive and destructive interference	7
2.2.3	Beam steering.....	7
2.2.4	Sound field zones	10
2.2.5	Beam width	11
2.2.6	Depth of field	11
2.2.7	Side lobes	12
2.2.8	Grating lobes	12
2.2.9	Cross coupling.....	13
2.3	Advanced focusing techniques	13
2.3.1	Dynamic depth focusing (DDF)	13
2.3.2	Synthetic aperture techniques	14
2.4	Ultrasonic phased array probe design	16
2.4.1	Phased array probe configurations	16
2.4.1.1	One-dimensional linear array	16
2.4.1.2	1.5-dimensional array.....	17
2.4.1.3	Two-dimensional array	18
2.4.1.4	Annular array	19
2.4.1.5	Segmented annular array (Rho Theta)	19
2.4.2	Common configurations of piezocomposite materials	19
2.4.2.1	2-2 Composite	20
2.4.2.2	1-3 Composite	20
2.4.2.3	0-3 Composite	21
2.4.3	Other piezocomposite design considerations	21
2.4.3.1	Volume fraction	21
2.4.3.2	Lateral vibrations	22
2.4.3.3	Flexibility	22
2.4.4	Basic array construction	22
2.5	Phased array probe performance	24
2.5.1	RF waveform.....	25
2.5.2	Frequency spectrum	26
2.5.3	Sensitivity.....	26
2.5.4	Ultrasonic beam profiling	27

2.5.5	Time of flight (TOF) normalization	27
2.5.6	Element-by-element validation	27
	References	28
3	Scanning patterns and ultrasonic views	29
3.1	Scanning patterns	29
3.1.1	Beam direction and conventions	30
3.1.2	Linear scan	31
3.1.3	Unidirectional scan	34
3.1.4	Bi-directional scan	34
3.1.5	Time based scanning, or manual scanning	35
3.1.6	Tandem probes	35
3.1.7	Tailored weld scans	36
3.2	Less common scanning patterns	37
3.2.1	Skewed scan	37
3.2.2	Helical scan	38
3.2.3	Spiral scan	38
3.2.4	Inspection sequences	39
3.3	Ultrasonic views (scan images)	40
3.3.1	A-Scan.....	41
3.3.2	B-Scan	44
3.3.3	C-Scan	44
3.3.4	D-Scan	45
3.3.5	E-Scan	46
3.3.6	S-Scan	46
3.3.7	Multiple views and layouts	49
3.3.8	Strip charts	51
3.3.9	Combined strip charts and other displays	52
3.3.10	Polar views	53
3.4	Time of flight diffraction (TOFD)	53
3.4.1	Description of TOFD	53
3.4.2	Comparing TOFD using conventional probes and using phased arrays	55
3.4.3	Combined TOFD and phased array	55
	References	56
4	Codes and calibration	57
4.1	Introduction	57
4.2	Codes and calibration	57
4.2.1	ASME.....	58
4.2.2	API	58
4.2.3	ASTM.....	59
4.2.4	AWS.....	59
4.2.5	Pipeline codes	59
4.2.6	Other codes	60
4.3	Code calibration of phased arrays	60
4.3.1	Calibration	60
4.3.2	Defect detection using S-Scans	62

4.3.3	Scan plans and coverage	63
4.3.4	Focusing.....	63
4.3.5	ASME section V: manual inspections using phased arrays	64
	References.....	65
5	Modeling and imaging	67
5.1	Introduction.....	67
5.2	Simple geometric beam models	67
5.3	Advanced geometric beam models.....	69
5.4	Advanced beam modeling software	71
5.5	Full beam propagation model.....	72
5.5.1	Beam propagation simulation.....	73
5.5.2	Phased array features.....	73
5.5.3	Compensation of beam aberration in irregular and heterogeneous components	74
5.5.4	Inspection simulation of a CAD component using S-Scans	75
5.5.5	Inspection of a nozzle with a matrix flexible array	76
5.6	Imaging	78
5.7	Advanced data plotting and visualization of weld defects	79
5.7.1	Two-dimensional data plotting.....	80
5.7.2	Three-dimensional data plotting – simplified features	82
5.7.3	Three-dimensional data plotting – advanced features	85
	References.....	87
6	Construction weld inspections	88
6.1	Weld inspections using manual phased arrays.....	88
6.1.1	Problem definition.....	88
6.1.2	Solution	88
6.1.3	Equipment used.....	89
6.1.4	Technique example	89
	References.....	90
6.2	T-joint weld inspections using portable phased arrays	91
6.2.1	Problem definition.....	91
6.2.2	Solution	91
6.2.3	Equipment	92
6.2.4	Technique example	92
6.3	Portable phased array inspection of newly fabricated pipe welds.....	94
6.3.1	Problem definition.....	94
6.3.2	Solution	94
6.3.3	Equipment used.....	94
6.3.4	Technique example	95
	References.....	97
6.4	Phased array pressure vessel inspection.....	98
6.4.1	Problem definition.....	98
6.4.2	Solution	98
6.4.3	Equipment used.....	99
6.4.4	Technique example	101
	References.....	103

6.5	Pipeline inspection using zone discrimination	104
6.5.1	Problem definition.....	104
6.5.2	Solution.....	104
6.5.3	Equipment used.....	105
6.5.4	Technique example	110
	References.....	111
6.6	Seamless pipe girth weld inspections.....	113
6.6.1	Problem definition.....	113
6.6.2	Solution	114
6.6.3	Equipment	114
6.6.4	Technique example	114
	References.....	117
6.7	ERW inspections in pipe mills	118
6.7.1	Problem definition.....	118
6.7.2	Solution	118
6.7.3	Equipment	119
6.7.4	Technique example	120
6.8	Friction stir weld inspections	122
6.8.1	Problem definition.....	122
6.8.2	Solution	123
6.8.3	Equipment used.....	123
6.8.4	Technique example	125
6.8.5	Eddy current array technique	127
6.9	Inspection of superaustenitic stainless steel welds using phased array ultrasonic testing	129
6.9.1	Problem definition.....	129
6.9.2	Solution	129
6.9.3	Equipment used.....	130
6.9.4	Technique example	131
6.9.4.1	Ultrasonic modelling	131
6.9.4.2	Phased array experimental validation	132
	Acknowledgments.....	136
	References.....	136
7	In-service weld inspections	137
7.1	Automated ultrasonic testing inspection of heavy-walled hydroprocessing reactors (AUT)	137
7.1.1	Problem definition.....	137
7.1.2	Solution	137
7.1.3	Equipment used.....	138
7.1.4	Technique example	139
7.1.4.1	Ultrasonic modeling and simulations	139
7.1.4.2	Experimental validation	143
	Acknowledgments	145
	References.....	145
7.2	Applications of ultrasonic simulations and phased array technology for optimization of detection and sizing of environmental cracking	146

7.2.1	Problem definition.....	146
7.2.2	Solution	146
7.2.3	Equipment used.....	148
7.2.4	Technique example	148
7.2.4.1	Ultrasonic modeling and simulations	148
7.2.4.2	Phased array experimental validation	150
	Acknowledgments	152
	References.....	152
7.3	Ultrasonic inspection for transverse defects in dissimilar metal welds.....	153
7.3.1	Problem definition.....	153
7.3.2	Solution	153
7.3.3	Equipment used.....	156
7.3.4	Technique example	156
	Acknowledgements	161
	References.....	161
7.4	Underwater nuclear vessel core spray weld inspection.....	162
7.4.1	Problem definition.....	162
7.4.2	Solution	162
7.4.3	Equipment	163
7.4.4	Technique example	163
8	Non-weld inspections	170
8.1	Portable phased array thickness inspection.....	170
8.1.1	Problem definition.....	170
8.1.2	Solution	170
8.1.3	Equipment used.....	171
8.1.4	Technique example	171
8.2	Fastener hole crack inspection using linear phased array	175
8.2.1	Problem definition.....	175
8.2.2	Solution	175
8.2.3	Equipment used.....	176
8.2.4	Technique example	177
8.3	Phased array railway axle inspection	179
8.3.1	Problem definition.....	179
8.3.2	Solution	179
8.3.3	Equipment used.....	179
8.3.4	Technique example	181
8.4	Development of in-service rail inspection systems using phased arrays.....	182
8.4.1	Problem definition.....	182
8.4.2	Solution	182
8.4.3	Equipment used.....	184
8.4.4	Technique example	184
	References.....	187
8.5	Phased array turbine shaft inspection	188
8.5.1	Problem definition.....	188
8.5.2	Solution	188
8.5.3	Equipment used.....	189

8.5.4	Technique example	190
8.6	Ultrasonic phased array inspection of bridge pins and eyebars	191
8.6.1	Problem definition	191
8.6.2	Solution.....	191
8.6.3	Equipment used	191
8.6.4	Technique example	194
	Acknowledgments	196
	References	196
9	Summary	197
	IIW Phased Array Glossary.....	198